

Component Control

1731 KETTNER BLVD
SAN DIEGO, CA 92101
Ph: 619-696-5400, Fax: 619-702-3522, Email: info@componentcontrol.com

Tear Down/Inspection

Work Order #: 100338

Date Printed: 1/21/2003

Time: 2:05:16 PM

Page: 1

Ship To:

ABJ Aviation Corporation
129 Air Service Way
Warehouse# 29
San Diego, CA 12299 USA

Ref #: R-49675

Phone #: 835-183-8595

Fax #: 835-183-8596

Email:

Code: AAC4

Site:

PN: .1880X.1280X.250

Descr: REAMER

Qty: 1.00

Station:

Make:

Model:

Mfg: LAERROME

TSN: 0

TSO: 0

TSR: 0

CSN: 0

CSO: 0

CSR: 0

SN#: 8957

Total Time:

is Time:

Engine Number:

Each Time:

:

:

Tail Number:

Serial Numbers:

Faults:

Found unit very dirty. Missing shipping clip and O-rings worn out.

Corrective Actions:

Cleaned throughout. Replaced O-rings and installed shipping clip.

PN	Description	Qty Needed
53-224	CLIP	1.00
0000001	0000001	6.00